

Oil Field Environmental Incident Summary

Incident: 20150320180256 **Date/Time of Notice:** 03/20/2015 18:02

Responsible Party: LANDTECH ENTERPRISES, LLC

Well Operator: LANDTECH ENTERPRISES, LLC

Well Name: FOSS SWD 1

Field Name: WEST BANK

Well File #: 90214

Date Incident: 3/20/2015 **Time Incident:** 07:30

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 96

Sec: 4

Qtr: SW SW

Location Description:

Submitted By: Kirk R Johnson

Received By:

Contact Person: Kirk R Johnson
PO BOX 1560
SIDNEY, MT 59270-1560

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2640 Feet

Distance Nearest Water Well: 2640 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 15 | Barrels | 10 | Barrels | | |
| Brine | 700 | Barrels | 700 | Barrels | | |

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Soil that was inside diked area that was contaminated will be removed and replaced

Action Taken or Planned:

Spill was contained with sump next to diked area, there was no mess around the tanks as the fluid ran into the overflow system 30 ft away from the tanks. Fresh water will be used to rinse any leftover oil and salt water down the drain to a vac truck. When the ground dries up we will remove any contaminated soil. Future action: Install additional radar to alarm for high tank levels.

Wastes Disposal Location: Salt water and oil is put in Landtech pit tanks for cleaning.

Agencies Involved: Dan Wells, NDIC Inspector

Updates

Date: 3/22/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking and constructed drain/containment system according to the report. NDIC retains oversight.